

PartsGo Industrial Parts RFQ Guide

Garbe Lahmeyer

PartsGo is an independent RFQ and sourcing platform unless a specific relationship is explicitly stated. This guide does not claim public stock, price, same-day shipment, or official distributor status.

RFQ checklist

- Exact brand name and part number
- Required quantity and target delivery country
- New, surplus, replacement, or repair preference if known
- Machine, line, or project context when it helps identify the part
- Urgency, deadline, and any acceptable alternatives

Common references

Garbe Lahmeyer 20007-408
Garbe Lahmeyer 415-30.02a
Garbe Lahmeyer 416-30.02a
Garbe Lahmeyer Brush (Coal) For Motor Typ: 10/127 G Obsolete
Garbe Lahmeyer Brush (Coal) For Motor Typ: A10/127 C Obsolete
Garbe Lahmeyer E10000 Obsolete
Garbe Lahmeyer E10000 P/N: D3d22341-0001 Obsolete
Garbe Lahmeyer En50
Garbe Lahmeyer Fge 180/24-4
Garbe Lahmeyer Fge 225/28
Garbe Lahmeyer Fsg201
Garbe Lahmeyer G0 100 L-H
Garbe Lahmeyer Iv 225 M4
Garbe Lahmeyer Nd50a
Garbe Lahmeyer Rd6-0.5 S
Garbe Lahmeyer Rd6 0.7s
Garbe Lahmeyer Rp50
Garbe Lahmeyer Snp 200 / 19,5
Garbe Lahmeyer Tfp200/19.5dc001f Obsolete, Replaced By Snp 200 / 19,5
Garbe Lahmeyer Type:E10000
Garbe Lahmeyer Vu50
Garbe Lahmeyer ZE6
Garbe Lahmeyer Zt 307180r Obsolete

How to request a quote

Visit <https://partsgo.net/request-quote> and send brand, part number, quantity, delivery country, company, contact details, and urgency.