

PartsGo Industrial Parts RFQ Guide

Gewefa

PartsGo is an independent RFQ and sourcing platform unless a specific relationship is explicitly stated. This guide does not claim public stock, price, same-day shipment, or official distributor status.

RFQ checklist

- Exact brand name and part number
- Required quantity and target delivery country
- New, surplus, replacement, or repair preference if known
- Machine, line, or project context when it helps identify the part
- Urgency, deadline, and any acceptable alternatives

Common references

Gewefa 01.043.010
Gewefa 05.008.255
Gewefa 05.009.130
Gewefa 05.024.080
Gewefa 05.024.081
Gewefa 05.024.082
Gewefa 05.024.083
Gewefa 05.024.084
Gewefa 05.024.085
Gewefa 05.024.086
Gewefa 05.024.087
Gewefa 05.024.088
Gewefa 05.032.704
Gewefa 05.032.902
Gewefa 05.032.904
Gewefa 05 056 105
Gewefa 05.056.210 M10 Å216; 7,0 X Vkt. 5,5 Mit Sicherheitskupplung
Gewefa 05.056.212 M12 Å216; 9,0 X Vkt. 7,0 Mit Sicherheitskupplung
Gewefa 05.056.216 M12 Å216; 9,0 X Vkt. 7,0 Mit Sicherheitskupplung
Gewefa 05.056.216 M16 Å216; 12,0 X Vkt 9,0 Mit Sicherheitskupplung
Gewefa 05 064 003
Gewefa 05 155 105
Gewefa 07.087.008 0120-160
Gewefa 07.087.009 0155-205
Gewefa 11.027.001
Gewefa 11.027.002
Gewefa 151.07.028.001
Gewefa 2303419 5006-105-00 Hsk-A63xÅ216; 12 X 110
Gewefa 28.07.066.003
Gewefa 28.07.066.052
Gewefa 30.02.036.127 Sk50 X Å216; 22 X 19 X 200
Gewefa 30.02.036.127 SK50 X O 22 X 19 X 200
Gewefa 30.02.036.131 Sk50 X Å216;27 X 21 X 160
Gewefa 30.02.036.132 Sk 50 X Å216; 27 X 21 X 200
Gewefa 30.05.031.021 Sk50 X Å216;25 X 80
Gewefa 30.05.031.021 SK50 X O25 X 80
Gewefa 30.05.031.604 Sk 50 X Å216; 12 X 100 Ad+bk

Gewefa 30.05.031.604 SK 50 X O 12 X 100 AD+BK

Gewefa 30.05.043.902

Gewefa 30.05.043.960

How to request a quote

Visit <https://partsgo.net/request-quote> and send brand, part number, quantity, delivery country, company, contact details, and urgency.