

# PartsGo Industrial Parts RFQ Guide

## Goot

PartsGo is an independent RFQ and sourcing platform unless a specific relationship is explicitly stated. This guide does not claim public stock, price, same-day shipment, or official distributor status.

### RFQ checklist

- Exact brand name and part number
- Required quantity and target delivery country
- New, surplus, replacement, or repair preference if known
- Machine, line, or project context when it helps identify the part
- Urgency, deadline, and any acceptable alternatives

### Common references

Goot 30w iron  
Goot Gs-108  
Goot PM-0050465  
Goot PM-0050805  
Goot PM-0050806  
Goot Px-201  
Goot Px-2rt-2bc  
Goot Px-2rt-2c  
Goot Px-2rt-3bc  
Goot Px-2rt-B  
Goot Px-2rt-Bc  
Goot Px-2rt-Sb  
Goot Px-501as-Replaced By Rx-701as  
Goot Px- 60rt- 1.6d  
Goot Px- 60rt- B  
Goot Rx-701as  
Goot Rx-802as  
Goot Rx-80hrt-0.5c  
Goot Rx-80hrt-0.8d  
Goot Rx-80hrt-1.2d  
Goot Rx-80hrt-1.6d  
Goot Rx-80hrt-2.4d  
Goot Rx-80hrt-2b  
Goot Rx-80hrt-3.2d  
Goot Rx-80hrt-4.5kh  
Goot Rx-80hrt-Lb  
Goot Rx-80hrt-Sb  
Goot Rx-852as  
Goot St-53sp  
Goot Svs-800as  
Goot Tp-100cp-07  
Goot Tp-100cp-13  
Goot Tp-100f  
Goot Tp-100k  
Goot Tp-100n-08  
Goot Tp-100n-10  
Goot Tp-100n-15

Goot Tp-100n-25  
Goot TP-200  
Goot Tq-77

## How to request a quote

Visit <https://partsgo.net/request-quote> and send brand, part number, quantity, delivery country, company, contact details, and urgency.