

PartsGo Industrial Parts RFQ Guide

Light Star

PartsGo is an independent RFQ and sourcing platform unless a specific relationship is explicitly stated. This guide does not claim public stock, price, same-day shipment, or official distributor status.

RFQ checklist

- Exact brand name and part number
- Required quantity and target delivery country
- New, surplus, replacement, or repair preference if known
- Machine, line, or project context when it helps identify the part
- Urgency, deadline, and any acceptable alternatives

Common references

Light Star 200/5
Light Star 200/5 3ct
Light Star 200/5 3ct Main Ct
Light Star 2P
Light Star 2p Bkm 6a
Light Star 300/5A KBD-42E
Light Star 50/5
Light Star 50/5 3ct
Light Star 50/5 3ct Main Ct
Light Star 62-1000-KBF
Light Star 62-1000-Kbf / 5a 15va
Light Star 62-1200-KBF
Light Star 62-1200-Kbf / 5a 15va
Light Star ABS125/100A
Light Star Abs125/100a Feeder Mccb
Light Star EBS32Fb
Light Star KAA08
Light Star Kaa08 Voltmeter=heat Tracing
Light Star KAA-80
Light Star Kaa-80 60/5a 50hz
Light Star KAB-08
Light Star Kab-08 600v Ac Voltmetr
Light Star Kab-08 [ac 600v]
Light Star Kab-08 Ac Voltmetr
Light Star KAB-80
Light Star Kab-80 600v 50hz
Light Star KAC-08
Light Star Kac-08 [dc 100a?100mv]
Light Star Kac-08 [dc 30a?100mv]
Light Star Kac-08 [dc 50a?50mv]
Light Star Kac-08 [dc 60a?50mv]
Light Star KAV08
Light Star Kav08 Ampmeter=heat Tracing
Light Star KBD-13
Light Star Kbd-13 60/5a 50hz 3.0cl
Light Star KBD-43
Light Star Kbd-43 200/5a 50hz 1.0cl

Light Star KBD-80
Light Star KBF-62
Light Star Kbf-62 [1000?5a 15va 1.0%]

How to request a quote

Visit <https://partsgo.net/request-quote> and send brand, part number, quantity, delivery country, company, contact details, and urgency.