

# PartsGo Industrial Parts RFQ Guide

## Mavilor

PartsGo is an independent RFQ and sourcing platform unless a specific relationship is explicitly stated. This guide does not claim public stock, price, same-day shipment, or official distributor status.

### RFQ checklist

- Exact brand name and part number
- Required quantity and target delivery country
- New, surplus, replacement, or repair preference if known
- Machine, line, or project context when it helps identify the part
- Urgency, deadline, and any acceptable alternatives

### Common references

Mavilor 00600000000000  
Mavilor 006000000a0100  
Mavilor 011000  
Mavilor 10.000 Basis  
Mavilor 112-Bt072a0030hn00  
Mavilor 112-Bt072a900099I7  
Mavilor 112-Bt073a0000k700  
Mavilor 113 B5074 A  
Mavilor 113-Bs073a000105d2  
Mavilor 113-Bs143900010qa1  
Mavilor 132-Ms040040000000  
Mavilor 132-Ms040040000000 Motor Mss-04, Basis  
Mavilor 132-Ms0400400g0100  
Mavilor 132-Ms060040000000, Typ Mss-6, Ohne Kabel B14, Ohne Tacho  
Mavilor 132-Ms0600400g0100, Typ Mss-6, Kabel 1,5m B14, D40/10v  
Mavilor 132-Ms0800402g0100  
Mavilor 132-Ms120040000065  
Mavilor 134-00080000000000 Motor  
Mavilor 134-00200000000000  
Mavilor 134-003000000a0100  
Mavilor 134-003000002a0100-Y190  
Mavilor 134-006000000a0100  
Mavilor 134-04500000000000 Dc Servo Motor  
Mavilor 134-Mo300-24467  
Mavilor 17201-670-0023 Tacho Generator  
Mavilor 17201-670-0040  
Mavilor 17201-670-0040 D-40, 10v  
Mavilor 17201-670-0040 (Tacho Rolivam Typ D40, 10 V)  
Mavilor 17201-670-0047 D-23a  
Mavilor 17201-670-0068  
Mavilor 62101MO4500-612-0031  
Mavilor 651-0269 (Elcam Code)  
Mavilor 670-0040  
Mavilor 670-0068  
Mavilor 86 61106e00 Nr. 70066265/116  
Mavilor AC-Servomotor Typ BLS40  
Mavilor AXLE. ROTOR – Mavilor Engine Rotor

Mavilor Bf122a302109a3  
Mavilor BI-074  
Mavilor BI-111

## How to request a quote

Visit <https://partsgo.net/request-quote> and send brand, part number, quantity, delivery country, company, contact details, and urgency.