

PartsGo Industrial Parts RFQ Guide

Rawet

PartsGo is an independent RFQ and sourcing platform unless a specific relationship is explicitly stated. This guide does not claim public stock, price, same-day shipment, or official distributor status.

RFQ checklist

- Exact brand name and part number
- Required quantity and target delivery country
- New, surplus, replacement, or repair preference if known
- Machine, line, or project context when it helps identify the part
- Urgency, deadline, and any acceptable alternatives

Common references

Rawet 03.A22A

Rawet 03.R11C

Rawet 5944 0109 Thermometer Pt35/70mm 1xpt100/A M12x1,75 4w 5m

Rawet 5944 0119 Thermometer Pt35/110mm 1xpt100/A M12x1,75 4w 5m

Rawet Acn-2p

Rawet Acn-I 0-5a / 4-20ma

Rawet ACN

Rawet Acn 0-5a / 4-20ma

Rawet Converter Px24 U/I? / 4-20ma

Rawet DIGIREG 03.R11C

Rawet Digireg 03.R11c Signalwandler Temperatur

Rawet Hth8 - Mtr9 -A3b -310 - 160 -150

Rawet ISOL100 I/I

Rawet ISOL400-DC

Rawet Isol400-Dc Coverter

Rawet Isol400/Dc Signalwandler

Rawet ISOL600 -50...220°C / 4-20mA 3w

Rawet P3s

Rawet PI121 0-5A / 4-20mA

Rawet Pi121 0-5a / 4-20ma Wandler

Rawet PL121

Rawet PI121 Messumformer Ac-Signale

Rawet PT100

Rawet Pt100/160 Resistance Sensor Type Pt50-2xpt100 350/200

Rawet Pt100/400 Resistance Sensor Type Pt50-2xpt100 650/500

Rawet Pt100/630 Resistance Sensor Type Pt50-2xpt100 780/630

Rawet PT3

Rawet PT31

Rawet PT35

Rawet PT35 8x110 M12x1,75 Pt100/A 5m 4w

Rawet PT35 8x70 M12x1,75 Pt100/A 5m 4w

Rawet Pt50

Rawet PT50 8x200/150 G1/2 Pt100/B

Rawet Pt50 8x200/150 G1/2 Pt100/B Temperatursensor Ip56 4w Max.200 Grad.

Rawet Pt55j 6 ? 140 /120 G 1/2 Pt 100/A

Rawet PTP10

Rawet Ptp10 Temperature Sensors For Outdoor Use

Rawet Ptp50
Rawet PTP50J
Rawet Pxn30.A Pt100

How to request a quote

Visit <https://partsgo.net/request-quote> and send brand, part number, quantity, delivery country, company, contact details, and urgency.