

PartsGo Industrial Parts RFQ Guide

Zero Max

PartsGo is an independent RFQ and sourcing platform unless a specific relationship is explicitly stated. This guide does not claim public stock, price, same-day shipment, or official distributor status.

RFQ checklist

- Exact brand name and part number
- Required quantity and target delivery country
- New, surplus, replacement, or repair preference if known
- Machine, line, or project context when it helps identify the part
- Urgency, deadline, and any acceptable alternatives

Common references

Zero Max 100466
Zero Max 100466 E1 Ccw
Zero Max 100470
Zero Max 100470 E41 Ccw
Zero Max 101079
Zero Max 12033922983
Zero Max 210-10DP
Zero Max 24033922983
Zero Max 45/59-49
Zero Max 6A18C
Zero Max 6a18c 3/8 W/Key X 5/8 W/Key
Zero Max 6A26C
Zero Max 6a26c Å248;25 Å248;25 Cdã174; Coupling Art.-Nr. (An_Cd)
Zero Max 6A30C
Zero Max 6a37ac
Zero Max 6a37c-32-38
Zero Max 6A45C ø32 ø40
Zero Max 6A45-SS
Zero Max 6a52c-40-45
Zero Max 80017
Zero Max 80323
Zero Max 80325
Zero Max 915-14S
Zero Max A030100
Zero Max Ae030100
Zero Max ANN_ALLG
Zero Max Ann_Allg Tt1x-C 3/8 X 3/8 5 0,6nm
Zero Max C011P
Zero Max C016p
Zero Max C130801
Zero Max C150806
Zero Max CD® Coupling Disc pack for size 37 CD coupling
Zero Max CD® Coupling Disc pack for size 52 CD coupling
Zero Max Cps10.2
Zero Max Cps 15.1-15b-15b
Zero Max Cps8
Zero Max CW-60-0-400

Zero Max E1 Ccw
Zero Max E2 Cw
Zero Max Etp T40

How to request a quote

Visit <https://partsgo.net/request-quote> and send brand, part number, quantity, delivery country, company, contact details, and urgency.